

POWER WIRING DIAGRAM FOR MAINFRAME