

List of CS-80 replacement components I used for MY (I say "MY") beloved CS

DISCLAIMER: I don't assume any responsibility for possible damage to your devices. I am not a tech, just a passionate fan of CS. So, the use of the following components is at your own risk.

I bought these components at the following stores (italian traders). The codes should be the same also in other Countries, but please check carefully before placing an order.

Sorry for the format of this file, it was written by my secretary copying and pasting the lines from the orders!

RS COMPONENTS

125-742 TRIMMER multiturn T93YB 10K

I used these to replace both the 8 trimmers of KAS and SH boards. Please notice that on the schematics the KAS trim pots are indicated as 100 K ! I measured them, they are 10 Kohms.

.....

521-1839 Capacitor, electrol., non polarized, 63V 1.0uF
414-9143 Capacitor, electrol., 50V 1.0uF
547-2927 Capacitor, electrol., 35V 10uF
414-9171 Capacitor, electrol., 50V 4.7uF

.....

526-537 CMOS 2-input quad CD4011BE

.....

527-596 Inverter CMOS hex CD4069UBE

.....

662-9660 AND Gate Quad 2-IN CMOS 14-Pin PDIP CD4081BEE4

FARNELL

Here I found these non polarized capacitors:

Farnell code 1499813

CAPACITOR ALUM ELECT 4.7UF, 50V, RADIAL NON POLAR

MOUSER

647-UFW1HR33MDD

Nichicon Aluminum Electrolytic Capacitors - Leaded
50volts 0.33uF

TARIC: 8532220000 ECCN:EAR99 COO:JP

647-UVR1H010MDD1TD

Nichicon Aluminum Electrolytic Capacitors - Leaded
50volts 1uF

TARIC: 8532220000 ECCN:EAR99 COO:MY

647-UKT1H470MED

Nichicon Aluminum Electrolytic Capacitors -
Leaded

50volts 47uF

TARIC: 8532220000 ECCN:EAR99 COO:JP

647-UVP1J4R7MED

Nichicon Aluminum Electrolytic Capacitors -
Leaded

63volts 4.7uF NON POLARIZED

TARIC: 8532220000 ECCN:EAR99 COO:MY

647-UVP1H100MED

Nichicon Aluminum Electrolytic Capacitors -
Leaded

50volts 10uF NON POLARIZED

TARIC: 8532220000 ECCN:EAR99 COO:JP